ST

6 JAN 1965

011114794

21 26Z 1965 JAN 5

Declassification Review by NGA/DoD

S E C R E T 052059Z

COPIES RECEIVED CyNo, Office Act. Rec'd Master File 105 ADMIN SEC BR P&DS CSD IPD PD PSD TID PAG CIA/PID DIAXX-4 SPAD -25X1 NSA LO DIAAP

Destroyed

- 1. CAMERA B-101 WAS USED IN MISSION 3981 FLOWN ON 3 JANUARY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.
 - 2. ORIGINAL NEGATIVE:
 - THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: A THREAD-LIKE OBSTRUCTION, APPROXIMATELY 0.4" LONG, ADHERING TO THE EDGE OF THE DATA CHAMBER IS PRESENT ON ALL FRAMES. A CLUSTER OF MINUS DESMITTY DOTS, UP TO 30 IN NUMBER, IS PRESENT IN THE OUTBOARD CORNERS OF EACH FORMAT THROUGHOUT THE MISSION. ANOTHER CLUSTER OF FOUR MINUS DENSITY DOTS OCCURS NEAR EACH FORMAT CENTER ON THE FIRST 1321 FRAMES. SPOT STATIC DISCHARGES OCCUR INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. NUMEROUS SHORT ABRASIONS, ACROSS THE ENTIRE FORMAT AND ROUGHLY PARALLEL TO THE FILM EDGES, ARE PRESENT ON FRANES 900 THROUGH 1458. MARKING PEN INK IS TRANSFERRED FROM THE HEAD LEADER TO THE FIRST FRAME (1200) PART 5. IRREGULAR PLUS DENSITY STREAKS OCCUR INTERMITTENTLY ON FRAMES 2125 THROUGH 2147 (END). A MANU-FACTURER'S SPLICE IS MADE IN FRAME 343.
- C. 9L SIDE: MINUS DENSITY DOTS, SPACED 1.55" APART, ARE LOCATED AT THE FOLLOWING DISTANCES FROM THE OUTBOARD EDGE OF THE FILM:

1.9" IN FRAMES 000 TO 005, 2.4" IN FRAME 754, 1.1" IN FRAMES 1426
TO 1429, AND 1.5" IN FRAME 1841. THERE ARE ALSO MANY SCATTERED
MINUS DENSITY DOTS CONTAINED IN FRAME 002. TWO MINUS DENSITY DOTS
LOCATED 1.5" AND 1.8" FROM THE OUTBOARD EDGE AND 0.7" FROM THE SUPPLY
SIDE OF THE FORMAT ARE PRESENT IN EACH FRAME FROM 950 TO THE
END OF THE MISSION. SEVERAL CHEMICAL SPOTS WERE NOTED ON THE EMULSION
FROM FRAME 757 TO THE END OF THE MISSION. A CRESCENT SHAPED FOG
PATCH 1.5" TO 2.5" LONG IS LOCATED ABOUT 6.5" FROM THE TAKE-UP
SIDE OF THE FORMAT AND 2.5" FROM THE OUTBOARD EDGE OF THE FILM.
THIS PATCH OF FOG IS PRESENT THROUGHOUT THIS MISSION AND IT HAS
BEEN REPORTED ON PREVIOUS MISSIONS.

- D. BOTH SIDES: OUTBOARD EDGE FOG IS PRESENT THROUGHOUT THE MISSION. THE TITLED FRAMES ON EACH SIDE ARE NUMBERED FROM ØØØØ TO 2147.
- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.
 - 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. THE PRINTING AND PROCESSING WAS GOOD.
- C. CLOUDS DEGRADED APPROXIMATELY 25 PERCENT OF THE MISSION.
 SECRET

-END OF MESSAGE-